











2+ | **85** | **2m** | **1 = 20,5m 2 = 16,8m 3 = 8,2m**


 Motor disability
 Sensorial disabilities
 Learning disabilities





Play value : **14**


 <p>sliding</p> <p>x1</p>	 <p>meeting</p> <p>x2</p>	 <p>resting</p> <p>x1</p>	 <p>handling</p> <p>x3</p>	 <p>thinking</p> <p>x3</p>	 <p>climbing</p> <p>x4</p>
--	--	--	---	---	--





Installation of equipment

Impact area =

-  Impact area
-  Free space



		
1	1,37m	182m ²
2	1,6m	11,5m ²
3	2m	19,5m ²



0



35h:0



3m³




213m²



5088kg



40kg



Proludic

2015-03-04